

Construction Guidelines

Amorphous thermoplastics do not have a well-defined melting point but have a relatively wide softening range. Therefore, welding parameters are less critical and there is reduced chance for thermal damage if the ultrasonic energy is on longer than necessary to obtain a good weld.

Semi-crystalline thermoplastics, on the other hand, have a clearly defined melting point. Most of these materials are sensitive to heat at temperatures above their melting point. Even short times at higher temperatures may cause thermal damage. There is air contact with molten plastic when the energy director is melting and spreading sideways; therefore, the material can crystallize before there is enough heat to weld the entire surface of the joint. Crystallized zones can crack and flake off from the welding area. The air contact may also cause oxidation of the plastic resin. Due to these possible problems, energy directors are not suggested for semi-crystalline materials.


Shear Joint 10

Shear joints are good for achieving a hermetic seal and for semi-crystalline thermoplastics in general. A shear joint is obtained with a step and little contact surface. The small surface and the resulting high energy flow cause rapid melting. The two parts slide into each other, forming a vertical weld joint. The sliding of the two melting surfaces prevents bubbles and limits air contact. The weld is homogenous and usually free of leaks. The regular and even welding procedure is easy to control. Since there is little air contact, cooling is slower and crystallization and flaking of the material is impossible. The integrity of a shear weld is influenced by the amount of overlap of the two parts.


The walls of the lower part must be supported in the welding zone to prevent bulging due to welding pressure, especially if the walls are thin.

Stud Welding 11


Stud welding is a special type of shear welding. It is an inexpensive solution for weldings where a hermetic seal is not required. A plastic stud molded on one part slides into a hole in the second part with bottom interference. The weld joint also provides positioning.




9 Energy director covered on both sides. The dimensions are critical.




10 Shear Joint Tolerance
 $a = 0.025$ to 0.05 mm
 Positioning height $b = 1.0$ mm min.
 Penetration $h = s/3 - 1.5 s$
 Overlap $= s/10 - s/5$.




10 Simple shear joint covered outside.




10 Simple shear joint covered outside with concentrated melting area.



10 Simple shear joint covered outside with weld flash space.



10 Double shear joint with both sides covered.



11 Stud Welding

Ultrasonic Welding

Ultrasonic welding of thermoplastics is cost effective because it cuts manufacturing time.

Ultrasonic welding is now a widely accepted process, having been first introduced in the early 1960's.

Most often, parts to be welded have been injection molded. The type of thermoplastic, the design of the parts to be welded and the design of the joint are of great importance but often neglected. To take full advantage of the benefits of ultrasonic welding it is advisable to choose the most favorable plastic material, provided there is flexibility to make a choice, and consider carefully the design of the parts, especially the joint.

It is advisable to take into consideration the different welding properties of amorphous and semi-crystalline thermoplastics when choosing the resin to be used. The selection of the plastic and the design of the parts are critical in getting dependable and reproduceable welds.

Of course, parts should be free of injection molding problems and inconsistencies such as bubbles, burned material, internal stress and sink marks resulting from the injection molding process.

Design Factors

Here are some factors to consider in order to achieve the best results with ultrasonic welding:

- ⇒ Strength requirements of the welded joint
- ⇒ Is a hermetic seal required?
- ⇒ Appearance requirements
- ⇒ Is flash permissible?
- ⇒ If there is a degree of flexibility on plastic resin, which resin will meet the design requirements and be best for ultrasonic welding?
- ⇒ Positioning and type of joint design
- ⇒ Parts design for ease of assembly before welding
- ⇒ Fixture design to hold the parts in position during welding
- ⇒ Will it be possible to make a horn to get the required ultrasonic energy into the joint?

Design of Parts to be Welded

Requirements for transmission of ultrasonic energy

The parts should be rigid if the energy must travel some distance to the joint. Softplastics do not transmit the energy well. The walls must be thick enough to prevent deformation of the welding zone. Thin walls tend to break due to mechanical force and ultrasonic exposure during the cycle.

Corners and Edges ①

All corners and edges should be radiused if possible. Ultrasonics can cause stress concentrations in sharp inside edges which can cause stress cracks or melting of the material.

Uniform Energy Delivery ②

Part design can influence the uniformity of energy delivery to the joint area. For instance, bends, sloping faces and openings in the energy path can reduce the strength of ultrasonic vibrations in the weld area.

Potential Troubles in Part Design ③

Extended part areas such as ribs, brackets, and studs may break during welding because of vibration and overheating. Inserted components such as springs or wires on electric components are also at risk. It is best to use generously rounded edges and corners and short welding times at low amplitudes. If necessary, potting compound such as silicon can be used to dampen the oscillation of electronic components, springs, etc.

Position of Joint Surface ④

It is best if the joint area is all in the same plane and the plane of the joint area is parallel to the horn surface. If the joint area has a step and is not in one plane, the unequal distances from the horn surface may produce uneven welding.


Mating of Parts to be Welded ⑤

Ideally, one part should mate with the other, and the parts should not be free to slide with respect to each other during the welding process. The fit should be close but not so tight that force must be used to put the parts together before welding. The ideal clearance will fall between 0.05 and 0.1 mm, depending on the size of the parts. The distance that one part should mate into the other should be at least one mm if possible. If it is not possible to design the parts so that they mate in the weld area, it is also possible to hold the parts in alignment by the fixture or horn.


Contact Surface between Horn and Part ⑥

Preferably, the contact surface between the horn and the part should be as large as possible and be flat. Some contouring of the horn surface is often possible.


If the surface of the horn is smaller than the contact area between the parts to be welded, welding may still be accomplished, but some of the energy may not get to the weld area. Also, higher force may be necessary to get a good weld. The higher force may lead to marking of the part surface under the horn.




All Corners should have a radius.




Poor or no welding at all in zone X.




Ultrasonically induced vibrations of extended parts.



Unequal distances L1 and L2; zone "a" not at right-angle to horn surface.



Tolerances of Mating Parts: a = 0.025 to 0.05 mm; b = 1.0 mm, minimum



Horn surface area of contact should be as large as possible; for instance, "a" should be larger than "s" if possible.

Highly polished or uneven surfaces in contact with the horn are subject to marking by the horn. The use of a protective thin membrane such as PE foil often reduces or eliminates the marking. An automatic foil feeder can be used to reduce labor.

Near Field Welding ⑦

The ideal part construction and design would place the contact surface of the horn as close to the welding area as possible.

The term "Near field welding" applies if the distance from the horn to the weld area is 6 mm or less. Applications which permit nearfield welding have the least problems although far field welding can also be very satisfactory if care is used.

Far Field Welding ⑧

In far field welding, the contact surface of the horn is greater than 6 mm from the welding area. The walls of the upper plastic part transmit the ultrasonic vibrations to the weld area, similar to a transmission line. Rigid, amorphous thermoplastic parts are excellent, low loss ultrasound conductors and best for far field welding. Rigid, semi-crystalline thermoplastics will absorb some energy, making far field welding somewhat more difficult. Soft, semi-crystalline thermoplastics have a high mechanical loss rate. Ultrasonic vibrations are therefore absorbed if the distance between horn and weld area is too great. Welding is difficult and melting of the contact area of the horn is likely to occur.

Fixture, Nest or Anvil


The parts to be welded can be mounted, centered and kept in place by a fixture. The part to be placed in the fixture should be close fitting, not tight and not loose. If the fit is too tight, energy will be lost to the fixture and welding will be difficult. If the walls of the parts to be welded are thin and not strong enough to support the force of the horn, the side walls may be supported in the welding zone with a temporary insert.

The two most important welding joints


There are two most frequently used basic welding joints: welding joint using an energy director (ED) and the shear joint (SJ).

Energy Director ⑨


The Energy Director is a V-shaped elevation on one of the two contact surfaces. It causes a line contact as the ultrasonic vibrations begin to melt the plastic. The line contact focuses the ultrasonic energy. As the melt progresses, the energy director turns fluid and flows to fill the space between the two parts. The downward force of the horn causes the melted material to spread over the entire contact surface. At this moment, the ultrasonic energy supply is shut off and the joint area, still under pressure, cools down in a short period of time, completing the weld. The energy director may be on either part. In the case of different materials it is recommended to place the energy director on the part with the higher softening and melting temperature or lower stiffness. This may be contradictory. In this case ask RINCO Ultrasonics for applications assistance.




Near field welding, L less than 6 mm




Far Field Welding, L more than 6 mm



Energy Director ED Height $h = s/10$ to $s/5$



Energy director covered on the inside. Material free to emerge on the outside.



Energy director covered on the outside. Material free to emerge on the inside.